SPEC SHEET + MEASUREMENTS



Wink[®] Men's Premiere Flex[™] V-Neck Top. WW5068

Product photo



- 78/20/2 poly/rayon/spandex
- V-neckline
- Shoulder badge loop
- Left chest pocket with pen slot
- Top-loading front pockets with interior right pocket
- · Side vents
- Wink[®] heat transfer logo at left hem
- Modern fit

CARE INSTRUCTIONS

Machine Wash Cold With Like Colors. Gentle Cycle. Use Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Remove Promptly From Dryer. Cool Iron When Needed.

Sketches





back

SPEC SHEET + MEASUREMENTS



Wink[®] Men's Premiere Flex[™] V-Neck Top. WW5068

PRODUCT MEASUREMENTS

	xs	S	M	L	XL	2XL	3XL	4XL	5XL
Body Length at Back	29	29 1/2	30	30 1/2	31	31 1/2	32 1/4	33	33 3/4
Chest	40	43	46	49	53	57	61	65	69
Set in Sleeve Length	9	9 1/4	9 1/2	9 3/4	10	10 1/4	10 1/2	10 3/4	11
Pocket Height	5 1/2	5 1/2	5 1/2	5 1/2	5 3/4	5 3/4	5 3/4	6	6
Pocket Width	5 1/4	5 1/4	5 1/4	5 1/4	5 1/2	5 1/2	5 1/2	5 3/4	5 3/4

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Set in Sleeve Length: Measure from Center Back neck to shoulder point to sleeve hem.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

SIZE CHARTS


	xs	S	М	L	XL	2XL	3XL	4XL	5XL
Chest	34-35	36-38	39-41	42-45	46-49	50-53	54-57	58-60	61-64

SPEC SHEET + MEASUREMENTS



Wink[®] Men's Premiere Flex[™] V-Neck Top. WW5068

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS

Please note: PMS code information is shown only when an exact match is available.

















Black PMS PROCESS BLACK C

Ceil

Navy PMS 654C

Pev 54C PM

Pewter PMS 432C

Royal PMS 2145C

Teal

White

Wine PMS 222C